

**APPENDIX B**  
**PHOTOGRAPHS**

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation



Photograph 1  
Taken April December 20,  
2012

Gravel surface in facility  
materials processing area.  
View looking north.



Photograph 2  
Taken April 9, 2012

Main facility entrance/exit  
onto 9<sup>th</sup> Street showing  
truck wash station in  
operation. View looking  
north.



Photograph 3  
Taken April 10, 2012

Northern facility  
entrance/exit onto Vine  
Street. View looking  
southeast.

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation



Photograph 4  
Taken April 9, 2012

Scrap handling operation  
along Vine Street. View  
looking northeast.



Photograph 5  
Taken December 20, 2012

Shredder fluff pile releasing  
steam. View looking east.



Photograph 6  
Taken April 10, 2012

Main facility entrance/exit  
onto 9<sup>th</sup> Street showing  
truck tracks.

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation



Photograph 7  
Taken April 10, 2012

View along Vine Street looking north. The facility is on the right (east) side of the photo.



Photograph 8  
Taken April 10, 2012

Street sweeper operated by the facility traveling along Vine Street near the north facility entrance. View looking North.



Photograph 9  
Taken April 10, 2012

Failure of the 12<sup>th</sup> Street culvert/road collapse near the southeast corner of the facility.

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation



Photograph 10  
Taken December 20, 2012

Unnamed tributary of  
Platin Creek looking  
upstream to the north from  
the 12<sup>th</sup> Street culvert near  
the southeast corner of the  
facility.



Photograph 11  
Taken December 20, 2012

Discharge from the facility  
to the unnamed Platin  
Creek tributary along the  
eastern facility boundary.



Photograph 12  
Taken December 20, 2012,

View of the unnamed  
Platin Creek tributary from  
the northeastern facility  
corner. View looking  
downstream to the south.

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation



Photograph 13  
Taken December 20, 2012

One of the holes in Joachim  
Plattin Ambulance District  
Building directly across  
from the facility shredder  
(viewed in background).



Photograph 14  
Taken December 20, 2012

Some of the material  
ejected from the facility  
shredder which has been  
collected at the Joachim  
Plattin Ambulance District  
building

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation



Photograph 15  
Taken April x, 2012

Establishing a transect in a residential yard for in-situ XRF analysis.



Photograph 16  
Taken April x, 2012

Conducting in-situ XRF analysis along a transect in a residential yard.



Photograph 17  
Taken April x, 2012

Collecting an incremental composite soil sample from a residential yard.

Photograph Log  
Shapiro Brothers Salvage Site  
Site Inspection/Removal Site Evaluation




Photograph 18  
Taken April 9, 2012

Plattin Creek tributary  
along eastern boundary of  
the facility showing metal  
debris in stream bed.



Photograph 19  
Taken April 9, 2012

Surface water and sediment  
sampling location at 12<sup>th</sup>  
Street bridge (SW01/SD02).  
View looking east.



Photograph 20  
Taken April 9, 2012

Surface water and sediment  
sampling location at Bailey  
Road bridge(SW03/SD03).  
View looking south.



Photograph 21  
Taken April 9, 2012

Surface water and sediment  
sampling location at 6<sup>th</sup>  
street bridge (SW02/SD02).  
View looking south.



Photograph 22  
Taken April 9, 2012

Surface water and sediment  
sampling location at Sunset  
Park (SW04/SD04). View  
looking east.