- - - - - - - - - - - - - - - - H e a d e r D a t a - - - - - - - - - - - - - - - -

Log # 005408 Owner:WILLMAN JOHN M St:MO Cnty:DEKALB
NW NW SE TRS: S07 T59N R32W
Alias:
Lat.:
Type well:Dry Hole Well
Long.:
Type log: S
Quad:UNKNOWN
Driller:V.C. DUGAN Date:06/1939
Driller Liscense #:
Confidential:Y Release Dt. /
Logger:HUNDHANSEN Date:06/1939

Elev.:1049 Elev.S Yield: 0 SWL:(a) H20 @:
T.D.: 207 base: DrDwn: 0 SWL:(b)

Bedrock at: 128 Samples saved:N Int. cored: 0 to 0
Top Fm.:PEDEE GROUP
Bot Fm.:LANSING GROUP
Problems:
Remarks:
More:O&G; CORE FOR STRUCTURAL CONTROL; SAMPLES, CORES, DRILLER'S LOG.

- - - - - - - - - - - - - - S t r a t i g r a p h y D a t a - - - - - - - - - - - -

Log #:005408

Top	Base	Name	--Lith-- Pr	Sc	Mn	Pri	Oc	Sec	Oc	Mnr	Oc
128	194	PEDEE GROUP	SH	LS	SD		0		0		0
194	207	LANSING GROUP	SH	LS			0		0		0

Printed on 05/16/94 at 14:02:02.

county Dekalb



sec 2 twp 59 rge 32

owner Willman, John M.

elev 1049 MGS# 5408 drillers ~~rge~~ log

farm Price No. 1 TD 207 fm TD line shows none

status date completed 6-8-39

remarks:

00017

WI004