



Jeremiah W. (Jay) Nixon, Governor

Sara Parker Pauley, Director

DEPARTMENT OF NATURAL RESOURCES

dnr.mo.gov

DNR Field Observations

May 29, 2013

Republic Services closed SC-3 leaving two of the original six RCPs to be completed while six of the remaining nine perimeter collection sumps, #2, 25, 24, 21, 20, and 18 were installed. Odors have been moderate to occasionally strong at locations to the north and northeast of the landfill including the Taussig/St. Charles Rock Road intersection and further to the northeast. During construction activities, a 12 inch gas header was broken near SC-3 and a leachate force main near PS-18 was cut as the perimeter collection sumps were being installed. All of these factors may have contributed to the odors. The department's air sampling contractor began a comprehensive air sampling event.



Photos are of department's contractor, SWAPE LLC and Republic Services' contractor, Stantec, doing side-by-side air sampling.



Work to abandon SC-3 above and below left.



Photo of completed SC-3.