



Welcome!
Missouri Department of Agriculture

**Division of Weights, Measures and Consumer
Protection
Petroleum Inspection Program**

7 9:26 PM

**Where I come from, old
tanks never die.**






Look how far we've come!



**DON'T LEAVE THE GAS PUMP
NOZZLE IN YOUR GAS TANK...**

Locations

- We have approximately 3,683 active retail service stations/bulk plants/airports/and marinas operating under the regulation of Chapter 414 RSMo.
 - 1,222 of those locations have aboveground storage tanks.
 - Currently the total number of AST's at active locations is 3800.
 - These locations have a total of 62,742 devices.
- 










RE
MIDGR
PREMIUM 5
READY TO GO FUELING
MDA-FUEL







CONOCO

Corrosion in Dispenser Sumps









GILBANY
VEEDER-ROOT Greensboro, NC

SERIAL NUMBER MDEN365930
#1-2 MW P

MODEL NUMBER NL1

NTEP CC NO. 02-019

For use with equipment specified in installation instructions.



SERVICE STATION HOSE NOZZLE VALVE
240 V. WITH UL LISTED INTERCHANGEABLE

UNIT
Voltage: 120
Hertz: 50/60
Amps: 13

Options:


SPEAKER
PUSH TO START
TOTALIZERS
CITY CENTER
INTERCOM


TRIPLE-DES PART 109104802
















Tank Inspection







Tank settling can create potential
for piping failure.
















Shim can affect the operation of the vent and in this case the overfill alarm.



THIS COMPONENT WAS TESTED TO AND MET THE FOLLOWING:

PRES.	2.5-6 IN. W.C.
VAC.	6-10 IN. W.C.
.05 CFH @	+2 IN. W.C.
.21 CFH @	-4 IN. W.C.

















What I planned.



what happened.