



Matt Blunt, Governor • Doyle Childers, Director

www.dnr.mo.gov

January 9, 2009

Mr. James M. Lanzafame
Environmental Manager
The Doe Run Company
Buick Resource Recycling Facility
HC1, Box 1395
Boss, MO 65440

RE: Permit Clarification, Buick Resource Recycling Facility, LLC, Boss, Missouri
EPA ID Number MOD059200089

Dear Mr. Lanzafame:

The Department of Natural Resources (department) has reviewed the November 13, 2008 submittal for a request for clarification concerning the type of waste that may be placed in the Slag Storage Area Landfill. If wastes generated from the facility recycling processes slag, soda slag, etc., do not fail the Toxicity Characteristic Leaching Procedure they do not require treatment prior to placement into the on-site landfill. Soils that may be generated during excavation on site that do not fail Toxicity Characteristic Leaching Procedure, may also be placed into the landfill without further treatment. The Buick Resource Recycling Facility may not use the landfill for any other types of solid waste without written approval of the department.

The department considers this a Class 1 permit modification requiring prior director approval. Buick Resource Recycling Facility must mail a notification letter to everyone on their facility mailing list within 90 days after the modification was put into effect, as outlined in 40 CFR 270.42(a)(1)(ii). Buick Resource Recycling Facility must send a copy of the notice to the department.

If you have questions regarding this letter, please contact Mr. George Fletcher, Environmental Engineer, at the Department of Natural Resources, Hazardous Waste Program, P.O. Box 176, Jefferson City, MO 65102-0176, or by phone at (573) 751-3553.

Sincerely,

HAZARDOUS WASTE PROGRAM

[Original signed by Richard A. Nussbaum]

Richard A. Nussbaum, P.E., R.G.
Chief, Permits Section

RAN:gfm

c: Mr. Michael B. Davis, U.S. EPA Region VII