County Andrew

sec. 6 twp. 59 rge 35

owner Home Oil Co.

elev. 1120 MCS# — spl. 20

farm DeBord No. ____ TD 255 fm@TD — shows oil/gas

status _____ date completed 3-30-39

remarks:

00002

275 71 N. 1" above 371 + 94.0 (1119.16)

27-F-30

MISSOURI GEOLOGICAL SURVEY AND WATER RESOURCES - ROLLA, MO.

COUNTY Andrew LOG NUMBER

COMPANY OR OWNER Home Oil Co - De Bordusel

FARM WELL NO.

LOCATION SEC. 6 T. 59 R. 35

CONTRACTOR V C Dugan Drilling Co

DRILLER V. C. Dugan TOOL DR. A. G. McClarey

COMMENCED Mar 20 COMPLETED Mar 30, 1939

PRODUCTION PLOTTED

CASING RECORD

WATER RECORD

SOURCE OF LOG Drilling Contractor ELEV. 1120

REMARKS area 3/4 acres on northline TOTAL DEPTH

function of Highway 71 and 275 CHEM. ANAL. NO.

FORMATION	THICK	DEPTH	FORMATION	THICK	DEPTH
Blue clay yellow mixed	0	42	Mixed lime & shale Breaks of lime in intervals 1 to 18" thick		
U P C Hard rock, seamy	42	60	Very gutty	160	200
Blue shale, slate firm	60	63	Hard lime rock	200	215
MDC Hard lime rock blue white texture	63	64	Mixed lime & shale breaks	215	227
Hard blue shale mixed lime showings, no sandstone,	64	86	Very hard lime	227	229
Mixed blue shales seamy, gutty	86	103	Mixed shale, lime shells gutty lime, shale breaks	229	240
Hard rock, lime showing	103	106	Oil and gas showing	240	244
Firm mixed shale, slate, gutty no sandstone	106	120	Lime gutty	244	246
LCC Hard rock	120	140	Shale & lime sand	246	250
Hard firm shales, slate, blue in texture lime shells present	140	160	Same	250	255 T.D.

1120
42
1078

Oread