

## **DHSS Follow-Up Review of Air Monitoring Data from the Bridgeton Landfill Area, July 25-July 29, 2013**

The Department of Health and Senior Services (DHSS) has reviewed air quality screening data collected by the Department of Natural Resources (DNR) at Bridgeton Landfill from the afternoon of July 25 to the afternoon of July 29, 2013. On June 7, DHSS began issuing follow-up reviews of the daily air quality screening data on a twice-weekly basis.

On April 23, DNR began routine, twice daily, surveillance of hydrogen sulfide, benzene, and odor levels around the entire periphery of the landfill. In addition, DNR has provided continuous monitoring of reduced sulfur compounds (reported as hydrogen sulfide), sulfur dioxide, carbon monoxide, and total volatile organic compounds (VOCs) at three fixed locations. DHSS has reviewed both sets of data to identify potential public health concerns for short-term health effects. Generally, samples are collected near the property boundary and dispersion is expected to reduce exposure downwind of the sample locations.

### Odors

DNR reported light and moderate to strong odors during this time period at locations east, north, south, northeast, and southeast of the landfill.

- Winds were predominantly from the south and southeast until July 26, northwest and east on July 27, and southwest on July 28 and July 29.
- During this time period, the DNR contractor detected light odors east, north, and northeast of the landfill on July 26, strong odors south and east of the landfill on July 27, light odors east and northeast of the landfill on July 28, and light odors south of the landfill on July 29 using a Nasal Ranger olfactometer.
- DHSS continues to recommend that during periods of objectionable odor, sensitive individuals should stay indoors as much as possible, avoid outdoor exercise, and seek medical advice for any acute symptoms. Symptoms associated with exposure to strong odors include headache, nausea, and fatigue. Symptoms generally associated with strong odors typically disappear once the odors dissipate.

### Hydrogen Sulfide and Other Reduced Sulfur Compounds

Hydrogen sulfide concentrations were well below levels of public health concern.

- The maximum concentration of hydrogen sulfide detected was 10 parts per billion (ppb) during routine monitoring. Hydrogen sulfide concentrations were detected by the Jerome meter, which is highly sensitive and specific to hydrogen sulfide.
- Average concentrations of reduced sulfur compounds did not exceed health-based guidelines for acute exposure to hydrogen sulfide, except for one hour on July 28 south of the landfill. These compounds detected by AreaRAE monitors are not just hydrogen sulfide but primarily another reduced sulfur compound with lower toxicity.

### Sulfur Dioxide

Average sulfur dioxide concentrations were below levels of public health concern.

- Sulfur dioxide was detected at monitoring locations east and west of the landfill. However, average concentrations of sulfur dioxide did not exceed 0.01 parts per million (ppm) and did not exceed health-based guidelines for acute exposure.

### Benzene and Total VOCs

Benzene was not detected in ambient air at any of the surveillance locations around the landfill.

- Previous sampling has shown that, while several VOCs are present in the landfill source gas, benzene may be a primary VOC of public health concern.
- At monitoring locations east and west of the landfill, average total VOC concentrations periodically exceeded a level that indicates a need for compound-specific sampling. However, these elevated concentrations were not verified by other AreaRAE monitors stationed in the same locations.

### Carbon Monoxide

Average carbon monoxide concentrations were well below levels of public health concern.

### Radiation Rates

Gamma radiation rates were well below levels of public health concern.

- Gamma radiation rates continue to be at levels that are at or near natural background levels.